

**Summary and**  
**recommendations**  
**following the annual**  
**review of the Public**  
**Footpaths of Y Felinheli**  
**2020**

**Llyr Evans, Emyr Gareth, Dafydd Gethin Huws, Nerys John,**

## Introduction

This review was carried out during the lockdown period of the COVID – 19 pandemics. The footpaths were used extensively by the residents and therefore any comment regarding overgrowth was particularly relevant.

During normal times overgrowth would have been worse with less use made of the footpaths. By the time this report is published the contractor has by now cut back the overgrowth on the footpaths noted on the contract details. It appears that the details of all the footpaths are not included within the contract. There will be a need to estimate the cost of this work by the contractor and include the work on future agreements.

The matters and recommendations of last year's review have been included (blue) as the work has not been sorted or partly sorted. The aim is to try and ensure that steps are taken to sort out the problems during the coming year.

It is acknowledged within the report that some of the recommendations is a matter of public safety and therefore of significant importance. These are noted here and within the report in red.

### Safety

**There is an urgent need to discuss with Gwynedd Council matters that may cause harm to the public on the following footpaths.**

- **Llwybyr Afon Heulyn Footpath 22**
- **Bryn y Waen to Penscoins Footpath 23b**
- **Bryn y Waen to ben ucha'r Inclein Footpath 23a**
- **Brynffynnon to Lon Bôst Footpaths 16 and 17**

There are clear patterns how some of the recommendations can be carried out and a summary of these can be found at the end of this report.

Several arrangements to litter pick have been done by Councilor Casi Roberts during the year. This has not been possible during the lockdown. We are aware that litter picking has been carried out by volunteers and this has made a difference. Support was provided by Gwynedd Council's Keep Wales Tidy Project Officer around the Cerrig yr Afon area.

### **Category 1**

*Footpaths that allow the movements of individuals. These are with significant use or create links within the village for public transport, car parks and local amenities.*

### **Category 2**

*Popular footpaths that are used for pleasure. These include footpaths around the community, circular routes, and access to beaches.*

### **Category 3**

*Footpaths that are used only occasionally but are still important to connect footpaths of categories 1 and 2.*

### **Category 4**

*Footpaths that are used less often but still play a part to create a full effective network. These can include proposed links between communities where there are not many presently in being and encourage people to walk.*

### **Category 5**

*Footpaths where there is no clear advantage and potential for them to be used as there are other footpaths of a higher category which can be used.*

Footpath Number	Category	<u>Annual Review Summary of the footpaths, Y Felinheli 2020</u>	Date of the review	Inspected by	Matters noted	Action
1	1	<b>Penrallt Footpath</b>  Londis to Penrallt	1/7/20	EG	<i>No sign from Penybryn</i>  <i>Footpath is not apparent due to no sign; there is a need to follow a private house access. There is a sign on Caernarfon Road but this is not sufficient, No sign where the footpath leaves the road to Penrallt Farm although the route is well defined.</i>	<i>Clerk to contact with Gwynedd Council regarding getting a new sign erected. This was discussed with Gwynedd Council on 9/10/2018</i>  <i>See 2019 recommendations.</i>
2	1	<b>Penrallt</b>  From Penrallt Farm over to Penrallt Terrace	1/7/20	EG	<i>Overgrowth as the footpath arrives at Penrallt Terrace.</i>  <i>Sign is not apparent at the bottom of Penrallt Farm towards the houses.</i>  <i>Gates are old and need to be renewed.</i>  <i>Sign from footpath 1 has been vandalized but still visible.</i>  <i>The footpath route is not apparent when moving from one field into another – arrow signs should make the route more apparent.</i>	<i>Contractor to be cutting the overgrowth by the end of October.</i>  <i>Clerk to contact GC for a new sign and to renew the gates. This matter was discussed in a meeting with GC on the 9/10/2018.</i>  <i>There is a need to discuss the signage again with GC</i>
3	2	<b>Pant yr Afallen</b>  Pant yr Afallen to Bush Road	6/8/20	DH	<i>No sign therefore it is not possible to say where the footpath starts from Bush road. There is a gate going into the field but there are cattle, calves, and a bull in the field.</i>  <i>No signs</i>  <i>No appropriate gates for walkers.</i>	<i>Clerk to contact GC. These matters were discussed at a meeting with GC on 9/10/2018.</i>  <ul style="list-style-type: none"><li><i>• Appropriate access to walkers into the field.</i></li><li><i>• No signs</i></li><li><i>• Appropriate sign to say that animals are in the field.</i></li></ul> <i>See 2019 recommendations</i>

4	1	<p><b>Allt Gam</b></p> <p>Pen-y-bryn to Gwylan Uchaf</p>	9/8/20	EG	<p><i>A lot of overgrowth</i></p> <p><i>Some litter</i></p> <p><i>Overgrowth including nettles especially at the two ends of the footpaths making it hard and unpleasurable to use.</i></p> <p><i>Some litter</i></p> <p><i>Hard to spot the sign from Gwylan uchaf due to tree branches.</i></p> <p><i>Steps in a bad way – many of the concrete steps are broken and are dangerous – risk of tripping</i></p>	<p><i>Contractor with be cutting back the overgrowth at the end of October.</i></p> <p>Discussion required with GC in regard to the steps, sign</p> <p>Contractor with be cutting back the growth at the end of October.</p>
5	2	<p><b>Bush Farm – Bonc via Bodandreg</b></p>	30/8/20	NJ	<p><i>No access from Bush Road. The sign from the stile is well apparent but a lot of overgrowth from there on.</i></p> <p><i>Overgrowth between Bush road and the second stile, about 300m from the bypass.</i></p> <p><i>A lot of overgrowth from the second stile making it impossible.</i></p> <p><i>Some litter on the bypass but good considering.</i></p> <p><i>Clear from Bodandreg</i></p> <p><i>Animals in the field</i></p> <p><i>Good signage except at Pen Bonc. Extra sign by the road to say that there is a need to turn to the left for Bodandreg and Bonc.</i></p> <p><i>No overgrowth.</i></p> <p><i>Gate at the end of the field for Bodandreg – animal trough by the gate – evidence that the land has been used by animals and is very muddy.</i></p> <p>The gate padlocked. Warning that there is a bull in the field.</p> <p>Second field for Bodandreg has</p>	<p><i>Contractor to be cutting back the overgrowth at the end of October.</i></p> <p><i>Sign required to warn about the animals in the field.</i></p> <p><i>Update GC that there is a lock on the gate. Access causing some uncertainty to walkers due to the bull in the field.</i></p> <p><i>Clerk to contact the Highways Department of GC to see what can be made to this part of the footpath to making it safer.</i></p>

					<p>young bull and cattle in it.</p> <p>Barking dogs whilst going through the farmyard at Bodandreg but they were locked away.</p> <p>Impossible to walk the footpath between Bush Farm and bypass. The area between the stile and Lon Bush has been cut back (Highways Department) thorn bush where the footpath is supposed to be.</p> <p>Problem in walking the bypass unless there is a guardrail to protect the walkers.</p>	
6	2	<p><b>Bodandreg Covert</b></p> <p><i>Bodandreg to Lon Llwyn</i></p>			<p>The sign is eroded in two places. A new one will be required soon.</p> <p>Sign has not been replaced.</p>	<p><i>The clerk to inform Gwynedd Council a new sign is required.</i></p> <p><i>2019 recommendations still stand</i></p>
7	2	<p><b>Bodandreg-Wern Isaf, Bethel</b></p>			<p>Footpath from Bodrandreg along the field to the border with Llanddeiniolen.</p> <p>Muddy at the gate at Bethel side, possible will be worse in the winter.</p> <p>No overgrowth problem at Bodrandreg side.</p> <p>Signs ok but nothing showing the way once you arrive at Wern Isaf from the Bodrandreg side.</p>	<p><i>The Clerk to contact Llanddeiniolen Community Council regarding the Bethel side of the footpath.</i></p> <p><i>Signage to be discussed with GC</i></p>
8	1	<p><i>Cerrig yr Afon</i></p>	<p><i>7/8/20</i></p>	<p><i>NJ</i></p>	<p><i>Litter in the river</i></p> <p><i>Gates where the animals got to the river for water – not sure if these have received some attention as mentioned previously.</i></p> <p><i>Fencing requires attention in one</i></p>	<p><i>The Clerk to arrange a meeting with the landowner where the river is – to see if we can co-operate to clear the litter.</i></p> <p><i>The Clerk to get a price for replacing the stakes for the fence.</i></p> <p><i>The Clerk to update with the</i></p>

					<p>or two places.</p> <p>Overgrowth from the land at the end of Tafarnygrisiau encroaching on the footpath.</p> <p><u>Litter – arrangement with owner and Daniel Griffiths of Keep Wales Tidy. The area cleared February 2020.</u></p> <p><u>Stakes have deteriorated and is problematic. There are some litter in being again that needs to be removed.</u></p> <p><u>round 5 that need to be replaced. The fence has been affected where walkers have tried to access the river.</u></p> <p><u>Overgrowth has been cut back between the Tafarnygrisiau and the first gate, but the thorns are now growing onto the footpath on both sides. The tree branches are starting to affect the bottom of the footpath.</u></p> <p>The surface – the pebbles placed originally have been washed away in places and the footpath is muddy.</p> <p><u>Signage – good but there is a need for a sign on the main road to show the footpath towards Tafarnygrisiau.</u></p>	<p>Farmer regarding the gates within the river.</p> <p>Contractor is to cut the overgrowth between Tafarnygrisiau and the first gate. The Clerk to make an addition to the agreement of the contractor regarding footpaths that are not included at present.</p> <p><u>Litter – there is a need for access through the fence to allow volunteers to collect the litter.</u></p> <p><u>Stakes – the clerk to make enquiries on getting prices to replace the current stakes and to secure the fence.</u></p> <p><u>Overgrowth – there is a need to relook at the present work required on the contractor’s agreement.</u></p> <p><u>Surface – there is a need to find out who is responsible and work towards place some new pebbles or slate waste on the footpath’s surface.</u></p>
9	2	Bonc-Bethel  Bonc to Bethel	7/8/20	NJ	<p>No sign by the gate</p> <p>Barbed wire across the path to the Bethel end of the footpath.</p> <p>Much overgrowth over the footpath on Bethel side of the footpath forcing walker to take another route. No signs by the gate by Tan y Buarth Bethel.</p> <p>No sign by the gate.</p> <p>A sign required by the gate on the border between the last field at the Felinheli and the first field</p>	<p>The clerk to contact GC regarding the sign this matter was discussed at a meeting with GC 9/10/18.</p> <p>The Clerk to arrange a meeting with the sub-committee and Llandeiniolen Community Council.</p> <p>2019 recommendations still stand.</p>

					<p><i>in Llanddeiniolen.</i></p> <p><i>Barbed wire is still in a dangerous position across the footpath at Bethel's end.</i></p> <p><i>Much overgrowth over the footpath on the Bethel's end making walkers takes another route.</i></p>	
10	2	<p><b>Tan-y-maes - Carreg Goch</b> Tan-y-maes to Carreg Goch</p>		NJ	<p><i>Although footpath is still registered there is no means for it to be used.</i></p> <p><i>No change since 2019</i></p>	<p><i>The Clerk to contact GC regarding this matter, GC have agreed in a meeting 9/10/2018 to discuss the matter with the landowner.</i></p> <p><i>2019 recommendations still stand</i></p>
11	2	<p><b>Carreg Goch - Crug Road</b> Carreg Goch to Ffordd Crug</p>		NJ	<p><i>Although footpath is still registered there is no means for it to be used.</i></p> <p><i>No change since 2019</i></p>	<p><i>The Clerk to contact GC regarding this matter, GC have agreed in a meeting 9/10/2018 to discuss the matter with the landowner.</i></p> <p><i>2019 recommendations still stand</i></p>
12	2	<p><b>Crug Road – Bethel West</b> Crug road westerly to Carreg Goch to Bethel</p>		NJ	<p><i>Although footpath is still registered there is no means for it to be used.</i></p> <p><i>No change since 2019</i></p>	<p><i>The Clerk to contact GC regarding this matter, GC have agreed in a meeting 9/10/2018 to discuss the matter with the landowner.</i></p> <p><i>2019 recommendations still stand</i></p>
13	2	<p><b>Carreg Goch - Bethel West</b> Carreg Goch to Bethel</p>		NJ	<p><i>Although footpath is still registered there is no means for it to be used.</i></p> <p><i>No change since 2019</i></p>	<p><i>The Clerk to contact GC regarding this matter, GC have agreed in a meeting 9/10/2018 to discuss the matter with the landowner.</i></p> <p><i>2019 recommendations still stand.</i></p>
14	2	<p><b>Bryn Cottages</b> Bryn Cottages to Bethel</p>	7/8/20	NJ	<p><i>Ramblers have made some significant work on the gates and the cutting back of the</i></p>	<p><i>Contractor will be cutting back the overgrowth at the end of October.</i></p>

					<p>overgrowth.</p> <p>New growth is impairing the use of the footpath from the Bethel end.</p> <p>Overgrowth on the Felinheli end especially around the gate by Bryn Cottages on the border of the first field.</p> <p>A mixture of twin, rope and barbed wire make it impossible to use the gate.</p> <p>The problematic gate has been sorted.</p> <p>Overgrowth on both gates on the Felinheli side.</p> <p>Overgrowth and a fallen tree on the Llanddeiniolen/Bethel side.</p>	<p>The Clerk to contact GC regarding the access via the gate by the road.</p> <p>The Clerk to arrange a meeting with the subcommittee and Llanddeiniolen Community Council.</p> <p>The Clerk to arrange a meeting with the sub-committee and the Llanddeiniolen Community Council.</p> <p>Contractor to be cutting back the overgrowth at the end of October.</p>
15	3	<p><b>Crug Road – Plas Llanfair</b></p> <p>Ffordd Crug to the west of Carreg Goch to Plas Llanfair.</p>	7/8/20	NJ	<p>Less overgrowth and the extra cut have made a difference.</p> <p>New overgrowth needs attention especially around the gates from Ffordd Crug towards the second field.</p> <p>GC have erected a new sign.</p> <p><u>Overgrowth reasonable although it was cut back in June.</u></p> <p>Overgrown tree has hidden the sign from the bypass.</p>	<p>Contractor cutting the overgrowth in October.</p> <p>Regarding this there is a need to discuss whether the Community Council is to arrange an extra cut during the season. An extra cut at the beginning of August?</p> <p>Contact GC regarding the overgrowth from the trees at the beginning of the footpath on the bypass.</p>
16	1	<p><b>Pistyll Brynffynnon</b></p> <p>Brynffynnon Road to Caernarfon Road west</p>	12/8/20	LIE	<p>New sign erected by Gwynedd Council.</p> <p>No rail where the new house has been built.</p> <p>Dangerous handrail– rusted on the Brynffynnon end (this noted in 2016and 2017 review) GC agreed in 9/10/2018 to price the handrail for the new financial year.</p> <p>Some overgrowth</p> <p>Some litter</p>	<p>The Clerk to contact GC regarding this matter.</p> <p>GC agreed in meeting dated 9/10/18 to:</p> <ol style="list-style-type: none"> <li>1.discuss with landowner 27 Brynffynnon to erect the handrail by the new building.</li> <li>2.renew rusted guardrail.</li> </ol> <p>There is a need to renew the surface. (it is understood from the contractor that this is the responsibility of Gwynedd</p>

					<p><i>Surface not good</i></p> <p><b>Problems with the handrail still exists. Covering place on the worse parts – this has been carried out some months ago.</b></p> <p><i>overgrowth</i></p> <p><i>litter</i></p> <p><b>uneven surface. Slipping slate steps especially in adverse weather conditions.</b></p>	<p><i>Highways – the Clerk to enquire.</i></p> <p><i>Contractor to cut back the overgrowth by the end of October.</i></p> <p><i>Clear the litter.</i></p> <p><i>See 2019 recommendations.</i></p> <p><b>There is a need to discuss a permanent remedy regarding the <i>handrail</i> and the surface with Gwynedd Council.</b></p>
17	1	<p><b>Stepiau Tai Railings</b></p> <p><i>Ffordd Brynfynnon to Ffordd Caernarfon east</i></p>	12/8/20	LIE	<p><i>Little overgrowth</i></p> <p><b>Loose handrail at the top and bottom.</b></p> <p><i>overgrowth</i></p> <p><i>uneven surface</i></p>	<p><i>Contractor to cut back the overgrowth by the end of October.</i></p> <p><b>A need to discuss a permanent solution to the handrail problem and resurfacing with Gwynedd Council.</b></p> <p><i>Contractor cutting the overgrowth by the end of October.</i></p>
18	1	<p><b>Stepiau Dinas</b></p> <p><i>Ffordd Caernarfon to Lan Mor</i></p>	12/8/20	LIE	<p><i>Little overgrowth</i></p> <p><i>Surface requires work.</i></p> <p><i>Overgrowth</i></p> <p><i>Litter</i></p> <p><i>Faded sign at the bottom.</i></p>	<p><i>Clear litter</i></p> <p><i>Clerk to enquire GC regarding improving the surface.</i></p> <p><i>There is a need to include this on the list for the contractor to carry out the work.</i></p> <p><i>There is a need to discuss the signing with GC again.</i></p>
19	2	<p><b>Plas Llanfair/Llanfair Woods</b></p> <p><i>Groeslon Cottage to Plas Llanfair to Goed Llanfair toi Lon Las Menai</i></p>	3/6/20	NJ	<p><i>Footpath closed temporarily (Bontnewydd bypass)</i></p> <p><i>Until February 2020</i></p> <p><i>Email sent 3<sup>rd</sup> June noting that part of the footpath not connected with the work on the new bypass needs attention.</i></p> <p><i>Signage needs attention, rights</i></p>	<p><i>The clerk to ask for a response to the June email.</i></p>

					of way and overgrowth. Waiting for a response from GC	
20	3	<b>Plas Llanfair Farm</b>  Fferm Plas Llanfair i Lon Las Menai	3/6/20	NJ	Footpath registered but not available for use.  The Lon Las is parallel to this footpath therefore it is not a priority	The Clerk to contact GC regarding this mater. CG agreed in a meeting dated 9/10/2018 to discuss with the landowner
21	1	<b>Rear Bangor Street</b>  Snowdon Street to back of Bangor Street	12/8/20	LIE	Little nettles on the side of the Graffiti  overgrowth  major overgrowth on Snowdon Street	Need to see if there is a way to get rid of the graffiti.  Graffiti is still needing to be removed.  A need to include the overgrowth on the contractor list of work to be done
22	1	<b>Afon Heulyn</b>  Nant Adda to the strait	9/8/20	EG	Considerable overgrowth between Ty Nant Adda and the road also on the path bypassing the house.  Some litter  No sign by the dry dock (showing that the footpath goes along the river)  No sign by the marina  Fence by the side of the vaynol wall requires mending.  Clear signs by Ty Nant Adda and Bangor Road. No arrow signs from the Bwythyn y Marina. No sign by the bridge by La Marina – coastal path is signposted but not the public footpath by the river.  <b>The Vaynol wall is in a dangerous condition. The slate coping stones have fallen in places ac in danger of falling in other areas. Overgrowth on top and behind the wall are pushing the coping stones into the footpath – a fall of 3 meters would cause a serious injury to</b>	The Clerk to contact GC regarding the signage. This matter discussed in meeting of 9/10/2018.  The clerk to make enquiries to see who is responsible for the repairs of the fence and to arrange repairs.  NJ has understood that it is acceptable for the contractor to cut the overgrowth on the path at Ty Nant Adda. Confirmation provided to contractor and the work will be carried out at the end of October.  2019 recommendations are still appropriate.  also:  The Clerk to send information to GC to ask GC for a response to the following:  <b>The need to make the Vaynol Wall safe – remove or replace the coping stones and remove the overgrowth on top of the wall that are pushing the coping</b>

					<p><b>a walker.</b></p> <p><i>The fence by the fallen wall is in a bad condition. Also, the fence by the end of the old slate bridge has fallen due to flooding.</i></p> <p><a href="https://www.rightmove.co.uk/commercial-property-for-sale/property-71602989.html">https://www.rightmove.co.uk/commercial-property-for-sale/property-71602989.html</a></p> <p><i>this advert suggests that the site at the end of the footpath is to be developed and that it is "a private gated development.</i></p>	<p><b>stones down.</b></p> <p><i>Signage needs to be discussed with GC.</i></p> <p><i>Research Will be required into this potential planning application.</i></p>
23a	2	<p><b>Bryn y Waen</b></p> <p><i>Bryn y Waen to Ffordd Pant yr Afallen</i></p>	6/8/20	DH	<p><i>The footpath from Bryn y Waen towards the mast has overgrown significantly at both ends. A substantial cut of overgrowth is required.</i></p> <p><i>Overgrowth underfoot is significant. The field is muddy.</i></p> <p><i>The footpath within the field where the mast is has been fenced but there is much overgrowth on the path. There is a possibility to walk parallel to the footpath along the field from the gate at Bryn y Waen, but it is not a public access. If a significant cut would be carried out to the overgrowth on the path the access to the path would be possible There is a need to regularly cut the overgrowth so that the footpath can be continued to be used.</i></p> <p><i>No sign at Pant yr Afallen end of the path.</i></p> <p><i>Too much overgrowth to walk the footpath.</i></p> <p><i>Closed by overgrowth.</i></p> <p><i>No sign at the Pant Afallen side.</i></p> <p><b>This footpath finishes on the bypass with the option of crossing the road to get to the footpath over the road.</b></p>	<p><i>There is a need to discuss as a Council to reopen the footpath.</i></p> <ul style="list-style-type: none"> <li><i>No arrangement with the contractor. Community Council need to decide if this footpath is to be included on the work list of the contractor.</i></li> <li><i>Consult with GP regarding the sign</i></li> </ul> <p><i>See 2019 recommendations.</i></p> <p><b>There is a need to discuss the safety of users on the bypass with the Highway department.</b></p>

					<b>Crossing the bypass is very dangerous.</b>	
23b	2	<i>Penscoins</i>  <i>Bryn Waen to Penscoins to Coedwig Cefn</i>	6/8/20	DH	<p><i>Bad access</i></p> <p><i>Overgrowth between Bryn y Waen and the bypass.</i></p> <p><i>Significant overgrowth between the bypass and Llwyn Onn. There is a need to brush cut the section of the path running alongside the by-pass so that users do not have to walk so close to the passing traffic. Lot of litter on the bypass and area close to the bypass.</i></p> <p><i>Signage after crossing the Felinheli border to Llanddeiniolen at Cefn Forrest the footpaths are hard to follow as there are several footpaths with no signage. Also, a report has been received from a member of the public that a bridge has fallen into the river on the Llanddeiniolen side.</i></p> <p><i>A fence of about 25m to protect users would reduce the risk of collisions with vehicles on the bypass. This part is dangerous and is on this part is at the upper end where there are 2 lanes, and the traffic is fast moving. Therefore, it is particularly dangerous. there there is two roads and more speed.</i></p> <p><i>Stile by Llwyn Onn is very slippery with overgrowth. Stile by Cefn Farm is also slippery.</i></p> <p><i>It is a very nice footpath but the part on the bypass is very dangerous. There is a need for a fence or a barrier of some sort here (25 – 30m) or cut back the overgrowth and the trees so that the footpath is not so near to the road.</i></p> <p><i>Access by Bryn y Waen is ok.</i></p>	<p><i>Contractor to cut back on the overgrowth at the end of October.</i></p> <p><i>The Clerk to contact the Highways Department.:</i></p> <ul style="list-style-type: none"> <li><i>• Litter on the side of the road</i></li> <li><i>• Need to make this area safety for users.</i></li> <li><i>• Brush cutting on the side of the road required.</i></li> </ul> <p><i>The clerk to arrange a meeting between the sub-committee and the Community Council of Llanddeiniolen to discuss the matters on footpaths on the Llanddeiniolen side.</i></p> <p><i>Clerk to enquire to see how we c ac to report back to the council to decide on the way forward.</i></p> <p><i>See 2019 recommendations.</i></p> <p><b>Need to discuss the safety of users on the bypass with the Highway department.</b></p> <p><i>The contractor is under the impression that highways are responsible for cutting the overgrowth between Llwyn Onn and the bypass.</i></p> <p><i>Signage to be discussed with GC again.</i></p>

					<p>Little overgrowth between Bryn y Waen and the Bypass. Need to cut back the overgrowth between the bypass and Llwyn Onn.</p> <p>No signage by the bend to Cefn – it is hard to see it. Not sure if there is a sign on the bypass by Bryn y Waen.</p> <p><b>A bit wet down to the bypass from the direction of Bryn y Waen.</b></p> <p><i>The stile at Llwyn Onn is very slippery with overgrowth. Stile by Cefn Farm also slippery.</i></p> <p><b>A fence is required by the side of the bypass.</b></p>	
24	1	<p><b>Hen Gei Llechi</b></p> <p><i>Garddfon to Hen Gei Llechi to Stryd Bangor</i></p>	12/8/20	LIE	<p><i>Fine</i></p> <p><i>Some overgrowth by the water</i></p> <p><i>Conditioning plant at the start</i></p>	<p><i>none</i></p> <p><i>The Clerk to enquire who would be responsible for the overgrowth in this area.</i></p>
<b>Footpaths not registered with Gwynedd Council</b>						
		<p><b>Cei Steps</b></p> <p><i>Stryd Bangor i Hen Gei Llechi</i></p>		NJ	<p><i>Fine</i></p> <p><i>Fine</i></p>	<p><i>none</i></p> <p><i>None</i></p>
		<p><b>Lon Las</b></p> <p><i>Pen-y-bryn to Seilo</i></p>		NJ	<p><i>No change since the last review</i></p> <p><i>Signage required:</i></p> <p><i>Seilo – over the road from Fourcrosses. From the Bangor direction turning left by the Lon Las by Ty Hen Stesion</i></p> <p><i>No change since the last review</i></p> <p><i>Signage required at:</i></p> <p><i>Seilo – fourcrosses</i></p> <p><i>From the Bangor direction turning left by the Lon Las by Ty Hen Stesion</i></p>	<p><i>The Clerk to contact GC – matter raised in meeting 9/10/2018.</i></p> <p><i>Signage to be discussed with GC again</i></p>

		<b>Rowen Dinas to Lan Mor Rowen</b>		NJ	<p><i>Sign required from Dinas Road to Rowen.</i></p> <p><i>Overgrowth. looks like a volunteer has cut back the overgrowth. More cutting is required.</i></p> <p><i>Fence to the field is broken needs to be repaired – possibility of horses to escape. Photographs attached.</i></p> <p><i>Volunteers have been litter picking at regular periods from the footpath and Beach.</i></p> <p><i>Sign from Dinas Road for Rowen required</i></p> <p><i>Attention to the fence is still required but barbed wire has been installed to keep the animals from straying,</i></p> <p><i>Overgrowth is still a problem. Contractor not been asked for a quotation to carry out this work.</i></p>	<p><i>The Clerk to contact GC regarding signage. Matter discussed in meeting of 9/10/2018.</i></p> <p><i>Community Council needs to decide if the overgrowth on this popular footpath is to be included in the work for the contractor.</i></p> <p><i>The Clerk to ask GC to contact the landowner to repair the fence.</i></p> <p><i>Signage to be discussed with GC again.</i></p>
--	--	-------------------------------------	--	----	--	--

## SUMMARY

### Cur overgrowth

There will be a need for a third cut every season with financial procedures in place or what was agreed on this as at the resolution of the Community Council's monthly Meeting September 2020.

### Litter Picking

Continuing with the arrangement for volunteer litter picks is important.

Maybe there is a need to look again at creating litter picking groups for different footpaths/areas within the village.

### Access

There are several examples of difficulties with access that require to be discussed with Officers of Gwynedd Council.

### Signage

There are constant problems with signage. It would be relatively easy to improve signage at many sites possible for volunteers to erect signs that are able to be placed easily with glue maybe. On gates or staked/

trees that are already in place. There is a need to discuss signage with Gwynedd Council to see how to solve this problem to improve the situation as it is now an old problem that is ongoing. The aim is to help with the walking of footpaths and to ensure that private land is not encroached upon.

### **Safety**

**A discussion is required with Gwynedd Council regarding matters that can cause injury to the public whilst using the following footpaths:**

- **Llwybyr Afon Heulyn (Footpath 22)**
- **Bryn y Waen to Penscoins (Footpath 23b)**
- **Bryn y Waen to ben ucha'r Inclein (Footpath 23a)**
- **Brynffynnon to Lon Bôst (Footpath 16 ac 17)**